# Approved For Release2902分配列 TSIAVRDP69B0040

000100029893-067 ATTACHMENT

CHANNELS JOINTLY

25X1A

# OXCART MISSION DATA Mission\_BSX003\_

Date Scheduled:	10 June 1967	-		1
Date Flown:	10 June 1967	-		$\frac{1}{r}$
Mission Complete	ed as Planned: Yes			
Mission Abort:				•
Ground.	N/A N/A			; ;
Mission Cancella	tion: N/A			· .
Reason:				·
Mission Recalled	:N/A			
Reason:				
Precautionary La	anding: N/A			
Reason:			· · · · · · · · · · · · · · · · · · ·	
Air Defense Rea	ction: None `			
				25X1D
Name to the second seco				
Remarks:	Spare aircraft utilized.			
				25X
		TTAN	NDLE VIA	

GROUP 1 Approved For Release 2002/06/To : CIA-RDP69B00404R@@@@@@@@@

OXCART/TRINE

TOP SECRET

Excluded from automatic

downgrading and

### r Release 2002/06/10 : CIA-RDP69B0 4R000100020003-0 Approved 👛

16 June 1967

# MEMORANDUM FOR THE RECORD

SUBJECT: Critique for OXCART Mission Number BSX003

- Subject mission was critiqued 15 June 1967. 1.
- Mission Data: 2.
  - Mission Number: BSX003
  - Date Flown: 10 June 1967
  - Area of Operation: North Vietnam c.
  - Mission Successful d.
  - Pilot Name: e.
    - Aircraft Number: 131 f.
    - Primary or Spare Flown: Spare
    - g. Take-off Time: Planned: 10 June 67/0200Z h.

Actual: 10 June 67/0249Z

Landing Time: Planned: 10 June 67/0723Z i.

Actual: 10 June 67/0717Z

Time Enroute: Planned: 5+23 j.

Actual: 4+28

- Departure Base: Kadena k.
- Landing Base: Kadena 1.
- m. Equipment:

25X1A

- Operations: Due to loss of fairing on primary A/C detected 3. during first refueling, Spare A/C was launched against second window timing.
  - Route(INS Plot Vs Planned): Canned route BSC010. First pass flown as briefed. Increased fuel consumption and rendezvous equip problems caused pilot to cancel second pass and return Kadena.
    - INS Terminal Error: 6.6 NM
    - INS Spec Error: 12.0 NM

Approved For Release 2002/86/19 6 A-RDP69B00404 ROUGH 1000 2000 B

GROUP 1 declassification

TOP SECRET

25X1A

# Approved Release 2002/06/10 : CIA-RDP69B0 4R000100020003-0

- b. Mission Generation: Satisfactory for both primary and spare take-offs.
  - c. Tanker Support and Operational Support: Satisfactory

d. Other Comments: Due INOP RDZ equip and low fuel						
reserves pilot elected to descend to						
area to establish contact with tankers. Article unloaded fuel and						
proceeded with tankers to A/R track. Fuel consump						
tion on climbout from A/R was higher than normal due excessive						
amount fuel used during ACCEL maneuver to become supersonic.						
Actual temperatures, at altitudes, were higher than standard.						

### 4. Weather:

25X1A

- a. Forecast Vs Actual: Actual wx better than forecast due to transparency of cirrus.
  - b. Weather Scout Reporting: Satisfactory
- 5. Intelligence: The second mission gave us a good data base on order of battle information on SA-2 & aircraft. Hanoi was clear but Haiphong was obscured by clouds and haze.
- a. Target Coverage, Actual Vs Planned: There were 16 out of 22 programmed Comor targets covered. There were 97 SA-2 sites photographed, of which four were newly identified. Thirteen first priority targets were covered in North Vietnam.

25X1A

# Approved Release 2002/06/10 : CIA-RDP69B0 4R000100020003-0

		b.	Quality of Take: Quality of photography good. At
5X1D	NA.	DIR,	ground resolutions
25X1D			There was some image
	sm	earin	ng, this was due to excessive vehicle roll and pitch rates
	Neg	gativ	es were under exposed about one full stop.
		c.	Hostile Reaction: None
		d.	Significant Findings: There was no evidence of offension
	sur	face	to surface missile equipment or facilities observed.
	18	SA-2	sites were occupied.
		e.	Take Movement:
			(1) Camera: Satisfactory
25X1D			
	6.	Ma	teriel:
		a.	Aircraft General:
			(1) Right rudder indicator oscillated (rudder O.K.)
			(2) Fuel consumption higher than normal.
			(0) ADG 50 D (ADD 11.11
			(3) ARC-50 Ext ADF unreliable.

Approved For Release 2002/06/10 : CIA-RDP69B00404R000100020003-0

TOP SECRET

(4) A/A TACAN unreliable.

# Approved Release 2002/06/10: CIA-RDP69B0 4R000100020003-0 Communications: a. Message Traffic: Satisfactory Significant Actions Taken: a. Initiated action to establish as additional missed A/R base. b. Implemented accident/incident reporting instructions.

25X1A

25X1A

7.

8.

9.

b.

Outstanding Actions Required:

settings to field. (OXC Ops/SSD)

Identify/clear/brief contacts

Provide minimum recovery kits

25X1D

Approved For Release 2002/06/10 : CIA-RDP69B00404R000100020003-0
TOP SECRET

Establish procedures for forwarding revised exposure